

**DEPARTMENT OF TRANSPORTATION**

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch

690 Walnut Ave.St. 150

Vallejo, CA 94592-1133

(707) 649-5453

(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 69.28**WELDING INSPECTION REPORT****Resident Engineer:**Siegenthaler, Peter**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** WIR-025614**Date Inspected:** 29-Jul-2011**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China**CWI Name:** Lu Hua Jie**CWI Present:** Yes No**Inspected CWI report:** Yes No N/A**Rod Oven in Use:** Yes No N/A**Electrode to specification:** Yes No N/A**Weld Procedures Followed:** Yes No N/A**Qualified Welders:** Yes No N/A**Verified Joint Fit-up:** Yes No N/A**Approved Drawings:** Yes No N/A**Approved WPS:** Yes No N/A**Delayed / Cancelled:** Yes No N/A**Bridge No:** 34-0006**Component:** OBG**Summary of Items Observed:**

On this day CALTRANS OSM Quality Assurance(QA) Inspector Mr.Shrikant Utekar was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. The QA Inspector observed and/or found the following:

ZPMC JETTY

MAGNETIC PARTICLE TESTING

OBG 13 EAST

This QA Inspector performed Magnetic Particle Testing (MT) of approximately 15% of the length previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an (MT) report on this date. The members are identified as OBG 13 East. The weld designations are as follows:

SEG3011C-162

SEG3011E-291

SEG3011E-292

SEG3011E-064

SEG3011G-208

SEG3011G-213

SEG3011G-218

---

## WELDING INSPECTION REPORT

( Continued Page 2 of 2 )

---

SEG3011G-244  
SEG3011H-002  
SEG3011H-005  
SEG3011H-140  
SEG3011H-161  
SEG3011H-164  
SEG3011J-150  
SEG3011J-190  
SEG3011L-277  
SEG3011B-003  
SEG3011D-003  
SEG3011K-158

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

### Summary of Conversations:

No significant conversations were reported on this date.

### Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, +(86) 1500 042 2372, who represents the Office of Structural Materials for your project.

---

<b>Inspected By:</b>	Utekar,Shrikant	Quality Assurance Inspector
<b>Reviewed By:</b>	Peterson,Art	QA Reviewer

---